


Determining Number of Battery Ports on Replacement FANUC A06B-6079 and A06B-6096 servo modules.


IMPORTANT: When placing an order for a replacement Absolute Pulse coder, you MUST specify whether you need a version with One or Two battery ports. Please use the images below to help identify which version you need.

- Example 6079 single axis using S1 configuration; no battery ports used.



Determining Number of Battery Ports on Replacement FANUC A06B-6079 and A06B-6096 servo modules.

- Example 6079 two axis using S2 configuration; 1 battery port used.



Determining Number of Battery Ports on Replacement FANUC A06B-6079 and A06B-6096 servo modules.

- Example 6096 using 2 battery ports.

